

95 Alliance Drive Rochester, NY 14623

 Phone:
 800-900-0679

 585-424-7325

 Fax:
 585-424-5823

 Email:
 sales@calkinstech.com

 Web:
 www.calkinstech.com

JOB#91670

October 00, 201x

PREPARED FOR:

PREPARED BY:

Paul Brokaw pbrokaw@calkinstech.com

Subject: Laser Alignment Report for pump#1 "Weiman" pump S/N 1748101 and pump#2 "Worthington" pump S/N 608518

Mike,

Thank you for your interest in Calkins Technical Products, Inc. and allowing CTP to provide laser alignment services for {Customer} in USA. Please see the following reports below of the 2 pumps (As Found and Final):





PRODUCTS, INC. Since 1980

CALKINS TECHNICAL

95 Alliance Drive Rochester, NY 14623


 Phone:
 800-900-0679

 585-424-7325

 Fax:
 585-424-5823

 Email:
 sales@calkinstech.com

 Web:
 www.calkinstech.com





PRODUCTS, INC. Since 1980

CALKINS TECHNICAL

95 Alliance Drive Rochester, NY 14623


 Phone:
 800-900-0679

 585-424-7325

 Fax:
 585-424-5823

 Email:
 sales@calkinstech.com

 Web:
 www.calkinstech.com





LUBRICATION FLUID SEALING PUMPS REPAIRS LASER ALIGNMENTS

95 Alliance Drive Rochester, NY 14623


 Phone:
 800-900-0679

 585-424-7325

 Fax:
 585-424-5823

 Email:
 sales@calkinstech.com

 Web:
 www.calkinstech.com



CALKINS TECHNICAL

PRODUCTS, INC. Since 1980



LUBRICATION FLUID SEALING PUMPS REPAIRS LASER ALIGNMENTS

CALKINS TECHNICAL PRODUCTS, INC. Since 1980 95 Alliance Drive Rochester, NY 14623

 Phone:
 800-900-0679


 585-424-7325

 Fax:
 585-424-5823

 Email:
 sales@calkinstech.com

 Web:
 www.calkinstech.com

"Weiman" Pump#1, S/N 1748101 "FINAL"





LUBRICATION FLUID SEALING PUMPS REPAIRS LASER ALIGNMENTS



95 Alliance Drive Rochester, NY 14623

 Phone:
 800-900-0679

 585-424-7325

 Fax:
 585-424-5823

 Email:
 sales@calkinstech.com

 Web:
 www.calkinstech.com

Mike,

Notes on the laser alignments of the 2 pumps.

-Pump#2 laser alignment went very well and smooth, "Excellent" Alignment was achieved. Did also adjust "outboard" packing gland to control the amount of water through the gland.

-Pump#1 laser alignment went well, "Excellent" Alignment was achieved, but in order to achieve alignment motor was removed and 1 of the "spacer blocks" under the motor was removed, in order to allow me to "move" the motor into alignment with the pump.

Service Technicians: Paul Brokaw would like to thank you for the opportunity to serve your company and your Laser Alignment needs. Please feel free to contact us with any questions and future needs.

Paul Brokaw Calkins Technical Products 95 Alliance Drive Rochester, NY 14623 585-424-7325 (Office) 585-545-1808 (Cell) <u>pbrokaw@calkinstech.com</u> (Email)



